

W.F. HARRIS LIGHTING 4015 AIRPORT EXT. RD. P.O. BOX 5023 MONROE, NC 28111-5023, USA (704) 283-7477 FAX (704) 283-6880

MODEL 50

MOUNTING INSTRUCTIONS

(FOR INSTALLATION BY QUALIFIED ELECTRICIAN)

- 1. TURN OFF POWER AT SOURCE.
- 2. REMOVE LENS FROM FIXTURE.
- CONNECT APPROPRIATE WIRES.
- 4. CONNECT GROUND WIRE TO GROUND HOLE IN MOUNTING PLATE, OR TO GROUND LEAD, OR TO GROUND HOLE IN CROSSBAR, WHICHEVER OF THESE METHODS WILL GROUND THE FIXTURE PROPERLY IN YOUR PARTICULAR SITUATION.
- 5. ALIGN KEYHOLE SLOTS IN FIXTURE BASE WITH SCREWS AT CORNERS OF RECESSED BOX. LET SCREW HEADS PASS THROUGH ROUND PORTION OF SLOT. ROTATE BASE SO SCREW HEAD IS OVER NARROW PORTION OF SLOT. TIGHTEN SCREWS TO SECURE FIXTURE TO MOUNTING SURFACE.
- 6. **INSTALL LAMP(S).** IF APPLICABLE.
- 7. INSTALL LENS AND TIGHTEN THE THREE SCREWS WHICH SECURE THE LENS TO THE MOUNTING PLATE.